

Display Screen

1) 1st display

Displays the measurement value or type of setting data.

When using the 3-STATE function, the backlight color changes.

2) 2nd display

Displays the unit or the parameter name of the measurement data or setting data.
Operation display
OUT1: The light turns ON in conjunction with the output set to the OUT1 terminal.

MODE key

· OUT2: The light turns ON in conjunction with the output set to the OUT2 terminal. • STOP: Lights ON when power is supplied after the time measurement function stops

following back-up power failure during power OFF. Lights OFF by setting time data. When using the product with lights ON, measurement data log cannot be recorded. • Om (Key): Lights ON at protect setting.

4) Temperature unit

When selecting Celsius in the temperature unit setting, °C is shown. When choosing Fahrenheit, °F is shown.

Segment display

_ 3																		
	Α	В	С	D	Е	F	G	Н	Ι	J	Κ	L	Μ	Ν	0	Ρ	Q	R
7SEG	R	Ь	Γ	d	Ε	F	ū	Н	Ē	Ļ	μ	L	ñ	п	ō	Р	9	r
11SEG	R	Ь	Γ	d	Ε	F	G	Н	Ē	Ц	K	L	Μ	Ν	ō	Р	D	R
	c	т	11	V	۱۸/	V	V	7	0	1	2	3	4	5	6	7	8	9
	5	1	0	V	VV		I	~	0		2	3	4	5	0	1	0	9
7SEG	5	F	U	u	U -	ū	У		ū	1	2	3	Ч	5	6	7	8	9
11SEG	5	Ŀ	11	1/	Ы	v	ų	7	0	!	2	7	ų	5	5	ņ	8	Q

Basic usage

Setting Examples

Applicable circuit type: 1-phase 3-wire					
Dedicated CT type: 5ACT					
Time: March 5, 2010, 17:15					
Dedicated CT type: 5ACT					

A. After checking the wiring, turn ON the power supply.

"HM5DE" is displayed and EEPROM is read ("URLE" is displayed for 16 sec max). When the power is turned ON for the first time, "E - L is displayed and STOP turns ON because time has not been set. 3 sec later, active power in measurement mode is displayed. (STOP remains ON).

B. Set applicable circuit type to 1-phase 3-wire.

- 1. Press the 🖃 key for more than 3 sec to go to applicable circuit type "DDL YP" in operation setting mode.
- Press the A key to shift to setting state. Press the A key to change the applicable circuit type from "∃P∃¼" to " IP∃¼", and then press the A key to confirm. C. Set dedicated CT type to 5ACT.

1. Press the 🔊 key to move to dedicated CT type "[] I.[.PL".

2. Press the \square key to shift to setting state. Press the \square key to change the dedicated CT type from " $I\square\square$?" to "5 \square ", and then press the \square key.

D. Set the time to March 5, 2010, 17:15.

To use the log function, time setting is required.
1. Press the l≥ key to move to time setting " *I L L M*".
2. Press the key to shift to setting state. Check that the year is "20 l0", and then press the ○ key.

- 3. Change the value of Month/Date with the key and shift the digit with the key to change the value from "□ 1/□ 1" to "□∃ /□5", and then press the key.
- 4. Change the value of Hour-Minute with the key and shift the digit with the key key to change the value from "□□ □□" to " I□ I□", and then press the key key. The content of the time setting will be saved and STOP will be turned OFF.
- 5. Press the 🖃 key for more than 3 sec to move to measurement mode (measurement start). When you move to measurement mode, the setting will be saved and "5RVE" is displayed.

This completes the basic settings.

Mode configuration and key operation

1) Mode configuration

Mode Group			Meaning	Necessity of operation and setting
Measurement mode		Basic level	Read the measurement data of the basic level	Operate only at reading
		Pro level	Read the measurement data of the Pro level	Operate only at reading
Protect	setting mode	;	Limit the function	Set only when needed
Setting	Operation	Basic level	Set the basic level function	Setting required at first setting
mode	setting mode	Pro level	Set the Pro level function	Set only when needed
	Communicat setting mode		Set the communication function	Set only when using the communication function

2) Key operation

Monitoring state is a state in which setting value is displayed in protect setting mode and setting mode. Setting state is a state in which setting can be changed.

Symbol	Basic Meaning	Mode	State	Operation	Description
ENTER key	 Mode switching Determination 	Measurement mode	Measurement history (current day)	press for more than 3 sec	Clear the currently displayed MAX and MIN value of the present day.
		Protect setting mode, Setting mode	Setting state	click	Determine the setting value.
		Operation setting mode	Monitoring state	click	Move to communication setting mode
		Communication setting mode	Monitoring state	click	Move to operation setting mode.
MODE key	 Mode switching Cancel 	Measurement mode	Present measurement value, measurement history	press for more than 3 sec	Move to operation setting mode.
			Measurement history	click	Move to present measurement value
		Setting mode	Monitoring state	press for more than 3 sec	Move to measurement mode.
			Setting state	click	Cancel setting state.
		Measurement mode, Setting mode	Pro level	click	Move to "PROLV" of the basic level.
>	 Transition 	Measurement mode	Present measurement value	click	Change parameters.
SHIFT key			Measurement history	click	Switch measurement history display.
		Setting mode	Monitoring state	click	Change parameters.
			Setting state	click	Change digits.
*	Shift to	Measurement mode	Present measurement value	click	Move to measurement history.
UP key	setting state		Measurement history	click	Move from measurement history.
	setting value	Setting mode	Monitoring state	click	Shift to setting state.
			Setting state	click	Change the setting value.
		Measurement mode, Setting mode	Basic level ("PROLV" remains displayed)	click	Move to Pro level.
@+>	·Reverse	Measurement mode	Present measurement value	click	Change parameters in reverse.
(Press the ≫ key while holding	transition		Measurement history	click	Switch the measurement history display
the 🖙 key)		Setting mode	Monitoring state	click	Change parameters in reverse.
			Setting state	click	Change digits in reverse.
(Press the ▲ key while	·Change the	Measurement mode	Measurement history	click	Transit measurement history in reverse.
holding the 🖾 key)	setting value in reverse	Setting mode	Setting state	click	Change the setting value in reverse.
@+0	 Mode switching 	Measurement mode	Present measurement value, measurement history	press for more than 3 sec	Move to protect setting mode.
		Protect setting mode	Monitoring state	press for more than 3 sec	Move to measurement mode.

Setting mode

Operation setting mode Basic level

	Item	Setting range (1st display)		Initial value	
Applicat	ole circuit type	ІР2W, ІРЭW, ЗРЭW, ЭРЧW	00.E YP	ЭРЭМ	IP2W: 1-phase 2-wire, IP3W: 1-phase 3-wire, 3P3W: 3-phase 3-wire, 3P4W: 3-phase 4-wire
	ed CT type	SA, SOA, IOOA, 200A, 400A, 600A	0 I.E.RG	IDDR	
Rated pri	mary side current value		02.5CE	5	Effective only when the dedicated CT type is 5A.
VT setting	VT primary side voltage value	NōNE, 220, 440, 3300, 6600, 11000, 22000, 33000	03.V.RG	NāNE	When the simple measurement is ON, sequentially measure the reactive voltage, VT primary voltage,
	VT secondary side voltage value	1 10, 220	¥.RG2	110	and VT secondary voltage. Unit: V
Current	low-cut value	0. / to 19.9	04.CUE	0.6	Unit: %
Pulse or	utput unit	I, IO, IOO, IK, 2K, SK, IOK, 20K, SOK, IOOK	OS.PL S	100	Unit: Wh
Display	refresh period	ōFF, 0.5, 1.0, 2.0, 4.0	06.REF	1.0	GFF is instantly updated. Unit: Sec
Averagi	ng times.	öFF, 2, 4, 8, 16, 32, 64, 128, 256, 5 12, 1024	07.8¥G	8	
Simple measureme		ōFF, ōN	08.5MP	ōFF	At ON, set voltage and power factor, Frequency is 50 Hz fixed.
setting	Fixed voltage value.	0.0 to 9999.9	<i>VLE</i>	1 10.0	Can be set only at simple measurement ON.
	Fixed power factor value.		PF	1.00	Can be set only at simple measurement ON.
Buzzer		āFF,āN	09. bZ	āΝ	Set the key operation buzzer sound to ON/OFF.
CO ₂ cor	nversion factor	0.000 to 99.999	10.052	0.387	Unit: kg-CO₂/kWh
Charge conversion setting (Rate setting and price unit setting)		ting and price JPY, USH, EUR, ENY, KRW		10.000 JPУ	Sequentially set the rate and price unit display. 4-digit price unit can be set.
Pulse conversion 1 setting (Pulse conversion target, factor, decimal point position and display unit)		C - E.d, C - I.d, C - 2.d, C - E.R, C - I.R, C - 2.R 0000 to 9999 0000, 000.0, 00.00, 0.000 R to Z, 0 to 9, 7, -, -, (Space)	12.57 1	C - I.d 000 I 0000 M3- I	Sequentially set the pulse conversion target, conversion factor, display unit. 4-digit display unit can be set. $L - L \cdot d$: Sum of pulse input counts $L - I \cdot d$: Pulse input count 1
(Pulse of factor, d	onversion 2 setting conversion target, lecimal point and display unit)	C - Ł.d, C - I.d, C - 2.d, C - Ł.R, C - I.R, C - 2.R 0000 to 9999 0000, 000.0, 00.00, 0.000 R to Z, D to 9, 7, , -, - (Space)	13.072	C - 2.d 000 I 0000 M3 - 2	$\mathcal{L} - \mathcal{L}.d$: Pulse input count 2 $\mathcal{L} - \mathcal{L}.\mathcal{R}$: Sum of total pulse input counts $\mathcal{L} - \mathcal{L}.\mathcal{R}$: Total pulse input count 1 $\mathcal{L} - \mathcal{L}.\mathcal{R}$: Total pulse input count 2
Time se (Year, m hour/min	nonth/day,	20 10 to 2099 0 1/0 1 to 12/3 1 00-00 to 23-59	IH.EEM	20 10 0 170 1 00-00	Year, month/day, and hour/minute should be set continuously. If it was canceled in process, all values will return to previous values. As soon as setting hour and minute, the settings are reflected.
Initialization		SEŁ, MR×, MīN, ĪNŁEG, M.PRā, LāG, ALL	IS.ENE	SEE	 5E Ł: Initialize all setting values except time setting. MR×: Initialize all the max value of parameters of the present day. MLN: Initialize all the min value of parameters of the present day. LNLEL: Initialize the total integral power consumption. MLPRo: Initialize the measurement values in the Proclevel in measurement mode of the present day. LoL: Initialize all the measurement thistories. RLL: Initialize set values other than clock time and all measurement histories.
Moving a setting	average time	00 1~ 120	16.RV E	120	Set the moving average time of the Moving average Current. Cancel it during the input or set a value out of the range, come back before a change.

Operation setting mode Pro level


Operation	n setting	mo	de Pro leve	I					
	Item		Setting range (1st display)	2nd display	Initial value			Remarks	
Event input s	setting		P.C SP, H - āN,	30.625	P.E 5P		ric power con input ON time	nsumption rate,	
Event input ? input mode s			NPN, PNP	3 I.PN I	PNP	NPN: None v PNP: Voltage	voltage input e input		
Event input 2 input mode s			NPN, PNP	32.PN2	PNP		NPN: None voltage input PNP: Voltage input		
Event input ? input mode s			N-ā, N-E	33.EN I	N-ā	N - ā: Norma N - E: Norma	<i>,</i> ,		
Event input 2 input mode s			N-ō, N-E	34.EN2	N-ā	N - ⊡: Norma N - E: Norma			
Measuremer	nt start time	(*1)	00-00 to 23-59	35.5 <i>E</i> C	00-00	Time setting	later than the	measurement end time cannot be made.	
Measuremer	nt end time (*1)	00-0 to 24-00	36.220	24-00	Time setting	earlier than th	e measurement start time cannot be made.	
3-STATE judgment tar	get		PWR, R, V, NōNE	40.EGE	NāNE	NGNE: 3-STA	ATE function	Irrent, V : Voltage, not used, When selecting " $3-5E$ " in t is automatically set to $N_0 NE$.	
3-STATE HIGH thresh	old		0. I to 150.0	Ч І.Н.ЕН (*2)	50.0			e LOW threshold or less. The operating value get to be determined. Unit: % (for rated input)	
3-STATE LOW thresho	old		0.0 to 149.9	42.L.EH (*2)	10.0	The operati		to the HIGH threshold or more. ries depending on the target to be rated input)	
3-STATE hys	steresis		0.0 to 19.9	4 <i>3.</i> 85 (*2)	0.0		ng value vai . Unit: % (for	ies depending on the target to be rated input)	
3-STATE col	or setting		GREEN, &RANG, REd	44.E ōL	See the remarks			DLE and LOW states. :: āRRNG, LOW: REd	
Output termi function setti			ōFF, P.ōUE, RLRRM	50.õ l	P.ōUĿ	P.allt: Integration When select	al power cons	umption pulse output, RLRRM: Alarm output , the screen moves to the ON/OFF	
Output termi function setti			ōFF, P.ōUE, RLARM	5 1.62	RLARM	When select		umption pulse output, <i>RLRRM</i> : Alarm output , the screen moves to the ON/OFF outputs.	
(Upper/lowe	Active power alarm output (Upper/lower thresholds, hysteresis and OFF-/ON-delay)		0.0 to 150.0 0.0 to 19.9 0.0 to 99.9	52.P.AL (*2)	See the remarks	Sequentially set the upper/lower thresholds, hysteresis and OFF-/ON-de Upper threshold: 80.0%, Lower threshold: 0.0%, Hysteresis: 5.0%, OFF-delay: 3.0 sec, ON-delay: 0.0 sec			
(Upper/lowe	Regenerated power alarm output (Upper/lower thresholds, hysteresis and OFF-/ON-delay)		0.0 to 150.0 0.0 to 19.9 0.0 to 99.9	53.R.AL (*2)	See the remarks	Sequentially set the upper/lower thresholds, hysteresis and OFF-/ON- Upper threshold: 80.0%, Lower threshold: 0.0%, Hysteresis: 5.0%, OFF-delay: 3.0 sec, ON-delay: 0.0 sec			
(Upper/lower	Current alarm output (Upper/lower thresholds, hysteresis and OFF-/ON-delay)		0.0 to 120.0 0.0 to 19.9 0.0 to 99.9	54.R.AL (*2)		Sequentially set the upper/lower thresholds, hysteresis and OFF-/O Upper threshold: 1/0.0%, Lower threshold: 0.0%, Hysteresis: 5.0%, OFF-delay: 3.0 sec, ON-delay: 0.0 sec			
Voltage alarr (Upper/lower hysteresis and	r thresholds,		0.0 to 120.0 0.0 to 19.9 0.0 to 99.9	55.1′.RL (*2)		Sequentially set the upper/lower thresholds, hysteresis and OFF-/OI Upper threshold: 1/II.II%, Lower threshold: II.II%, Hysteresis: 5.II%, OFF-delay: J.II sec, ON-delay: II.II sec			
Power factor (Upper/lower hysteresis and	r thresholds,		0 to 100 0 to 19 0.0 to 99.9	56.PF.R (*2)	See the remarks	Upper thres	wer thresholds, hysteresis and OFF-/ON-delay. Lower threshold: 0%, elay: 3.0 sec, ON-delay: 0.0 sec		
Reactive pov (Upper/lower hysteresis and	r thresholds,	·		57.0.AL (*2)	remarks	Upper thres	wer thresholds, hysteresis and OFF-/ON-delay. Lower threshold: 0.0%, delay: 3.0 sec, ON-delay: 0.0 sec		
Integral pow saving selec			-W, V AR.d, V AR.G, V AR.A	60.c.SL	- W	- #: Integral regenerated power consum # RR.d: Integral leading reactive power of # RR.L: Integral lagging reactive power con # RR.R: Integral total reactive power cons		active power consumption active power consumption	
Automatic rotatic	on Automatic ro	tation	āFF,āN	6 I.REE	ōFF	At ON, set th	he transition	time.	
setting	Transition		/ to 99	REIM	3	Can be set of	only at autom	natic rotation ON.	
Measurement parameter display selection			ōFF,ōN	62.d.5L		conversion v power consu	alue, pulse co mption, integr	of the measurement mode. For the charge nversion 1 and 2, integral regenerated al leading/lagging/total reactive power temperature, these initial values are <i>GFF</i> .	
Display lighting time		0 to 99	63.d5P	0	🛙 is always lighting, Unit: Min				
Incorrect voltage wiring detection			64.V - E	āN					
Simple Temperature unit			,	65.d-U	[Sequentially correction va		perature unit and the temperature	
setting Correction value		-50.0 to 50.0	E.Rd	0.0			Fahrenheit, Unit: °F		
*1 It applies to the pulse input count, power consumption rate, puls 3-STATE integration time. *2 When thresholds or hysteresis is set, the operating value which			<i>·</i> •		,	5 1 1			
Commun	Communication setting mode								
lte	em		Setting rang	je (1st display))	2nd display	Initial value	Remarks	
Protocol sele	ect	EāM	PF,Mādb			80.PSL	EGMPF	LoMPF: CompoWay/F, Modbus	
Unit No.			npoWay/F: 🛙 to 🤋			8 I.U.Nã	1		
Baud rate		1.21	r, 2.4K, 4.8K, 9.6K	K, 19.2K, 38.4	łK –	82.6PS	9.6K	Unit: bps	
D	(1 (4 4))	10 0			I	0.7.1.6.11		hi se i se la	

	<u> </u>			
Item	Setting range (1st display)	2nd display	Initial value	Remarks
Protocol select	EōMPF,Mōdb	80.PSL	EGMPF	LoMPF: CompoWay/F, Modb: Modbus
Unit No.	CompoWay/F: 1 to 99, Modbus: 1 to 99	8 I.U.Nā	1	
Baud rate	1.2K, 2.4K, 4.8K, 9.6K, 19.2K, 38.4K	82.6PS	9.6 <i>K</i>	Unit: bps
Data bit length (*1)	П, В	83.LEN	7	Unit: bit
Stop bit length (*2)	1, 2	84.5 <i>6</i> E	2	Unit: bit
Vertical parity	NāNE,ādd,EVEN	85.PRE	EVEN	
Time to wait for sending	🛙 to 99	86.5dW	20	Unit: ms

*1 When protocol is Modbus, data bit length is 8-bit fixed. *2 When vertical parity is NONE, the length cannot be set due to automatic setting. When vertical parity is NONE, the length is 2, when vertical parity is ODD or EVEN, the length is 1.

Protection mode

Setting			Limit content			
content Displayed value transition		Move to setting mode	Move to pro level	Clear measurement history	Change setting content	
0	Yes	Yes	Yes	Yes	Yes	
1	Yes	Yes	Yes	No	No	
2	Yes	Yes	No	No	No	



easured value	Saving period	Remarks
onsumption	5 min.	Save two days' measured values every 5 min.
	1 hour	Save 25 hours' hourly values which are converted from measured values saved every 5 min.
	1 day	Save 8 days' values measured between 00:00 and 24:00.
	1 month	Save 13 months' values measured for a month.
rrent, voltage and ninimum values)	1 day	Save 8 days' values measured between 00:00 and 24:00. (After saving, measured values are reset.)*
e Current num values)	_	Save the current maximum values of the moving average time. (The moving average current with a product Ver.3.0.)
nt	5 min.	Save two days' measured values every 5 min.
onsumption rate time Il power consumption	1 day	Save 8 days' values measured between 00:00 and 24:00.
ition time	1 day	Save 8 days' values measured between 00:00 and 24:00.
ated power consumption power consumption	5 min.	Save two days' measured values every 5 min. Save only items selected in the setting.
nt inputs ntegral power consumption ntegration time	5 min.	Overwrite save the measured value every 5 min.

tion of error	Display	Operation	Restoration method
clock time has not	E-E I	Indicates error at startup and "STOP" is turned ON. Measurement stops and operation disabled during error indication.	Time setting
rror (RAM error) (*1)	E-MI	Measurement stop, operation disabled	Hardware repair (*2)
(*1)	E-M2	Measurement stop, operation disabled	Hardware repair (*2)
failed (*1)	E-M3	Measurement stop, operation disabled	Hardware repair (*2)
ie error (*1)	E-M4	Measurement stop, operation disabled	Hardware repair (*2)
ige input (*3)	E-5	Displays error and measurement value alternately and continues measurement.	Restore the input signal within to the rated range.
ent input (*3)	E-52	Displays error and measurement value alternately and continues measurement.	Restore the input signal within to the rated range.
it error (*3)	E-53	Displays error and measurement value alternately and continues measurement.	Restore the input signal (voltage) within to the rated range.
detection (*4)	E-54	Displays error and measurement value alternately and continues measurement.	Correct the input signal (voltage) wiring in phase sequence.

nomenon	Description	Point to be checked			
rrent are measured ver is not correctly	Transformer) been correctly wired	If negative electric power is measured, it might be all the CTs have been mounted oppositely. On the other hand, if the measured value is nearly 0, it might be one of the CTs has been mounted oppositely.			
	Is the voltage phase sequence correct?	If the voltage phase sequence is not correct, electric power cannot be measured correctly. Perform correct wiring.			